


LE 03 User Interface_01



LE 03 User Interface_01

START READY for RECORDING or ON AIR !

LIN / MIC 1/2 Stereo Mode
HP Level at 50%
DIGITAL OUT and USB Level at 75%

Press both Buttons simultaneously

The LED shows all your Actions

Press both Buttons simultaneously



LE 03 User Interface_01

LEVEL for HEAD PHONE or DIGITAL OUT and USB

HEAD PHONE

- 1 hold down the **DO** button
- 2 press the **HP** button once

DIGITAL OUT and USB

- 1 hold down the **HP** button
- 2 press the **DO** button once

HP button increased Level in 1dB steps
hold down the Button continuously increasing

The LED shows all your Actions

DO button decreasing Level in 1dB Steps
hold down the Button continuously sloping

The last Shot will be saved



LE 03 User Interface_01

MONO MODE on/off

LIN / MIC 1 is the Mono Input
on Headphone L / R

1 hold down the **HP** button

LED is on

2 press the **DO** button twice



LE 03 User Interface_01

REF GENERATOR on/off

1kHz -9dBFS on USB and Digital Out

1 hold down the **HP** button

LED flashes fast

2 press the **DO** button 3 times



LE 03 User Interface_01

HEAD PHONE on/off (N-1)

LIN / MIC Inputs switched on/off from the Headphone

2 press the **HP** button twice

The LED shows all your Actions

1 hold down the **DO** button

